



Set-up instructions for SH3222A:

Step 1: Connect 2x the longest pipes horizontally using 2x straight connectors on the sides.

Step 2: Connect 4x mid-length pipes vertically on all four corners into the connectors.

Step 3: Repeat Steps 1 & 2 for the middle level using 2x E-shaped connectors.

Step 4: Repeat Step 1 for the top level using 2x E-shaped connectors.

Step 5: Place the 3x wire meshes on all levels.